

Installation of DSG and other types of double clutch gearboxes

Below instructions are extra important to check since each one individually can cause a gearbox failure that is not covered by warranty. NOTE! The instructions should be seen as a complementary reminder in addition to the car manufacturer's instructions.

- Extract the error codes from the car's entire system and note them before removing the old gearbox.
- □ In the event that the oil cooler is not supplied with the automatic box, clean the cooler and the pipes carefully (flush). The cooler should be replaced if the defective gearbox oil contains metal chips or foreign particles.
- Always check that all motor and gearbox guide pins are in place.
- Check that the **flywheel** is undamaged.
- □ Use oil recommended by the car manufacturer or Hellsten Gears AB when filling/ leveling.
- Delete all error codes before performing a basic setting.
- □ A **basic setting** must be carried out after installation. You may have to redo a basic setting several times in case of problems.
- □ Check oil level before and after test run.
- Check that there is **no leak** after test run.
- **Oil from mechatronics** must not have leaked through vent holes.

WARRANTY ONLY APPLIES IF THESE INSTRUCTIONS HAVE BEEN FOLLOWED. CONTACT TECHNICAL SUPPORT IF ANYTHING IS UNCLEAR.

ADDRESS Varbergsvägen 416 SE-439 73 Fjärås Sweden CORPORATE IDENTITY NO. 556409-1857 COMPANY RESIDENCE Kungsbacka Sweden

VAT NO. SE556409185701 E-MAIL info@hellstengears.com SWITCHBOARD +46 300 - 742 20 WEB www.hellstengears.com